


CORNER RECORD

Document Number 200-173-10

City of MILL VALLEY and County of MARIN, California

Brief Legal Description: LOT 5 OF THAT MAP ENTITLED "MAP OF PARK HILL, UNIT 1", FILED 1/30/1963, PER VOLUME 11 OF MAPS, AT PAGE 61, MARIN COUNTY RECORDS



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other

Date of Survey 10/14/2015

COORDINATES (Optional)

N: _____
E: _____
Zone: _____ NAD 27 NAD 83
Elev: _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial

CORNER -- LEFT AS FOUND FOUND AND TAGGED ESTABLISHED REESTABLISHED REBUILT

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

FOUND STANDARD WELL MONUMENTS PER VOLUME 11 OF MAPS, AT PAGE 61, MARIN COUNTY RECORDS

A description of the physical condition of the monument as found and as set or reset: _____

ORIGINAL CORNERS NOT FOUND. SET POINTS AS SHOWN ON REVERSE.

SURVEYOR'S STATEMENT:

The corner record was prepared by me or under my direction in conformance with

the Land Surveyors' Act on JUNE 7 2016

Signed: [Signature] L.S.# 8080



COUNTY SURVEYOR'S STATEMENT:

The corner record was received MARCH 10, 2016

and examined and filed JULY 7, 2016

Signed: [Signature] R.C.E or L.S. No. 7821

Title: County Surveyor



COUNTY SURVEYOR'S COMMENT: _____

AMERICAN LAND SURVEYING, INC.
 1390 Market St, #303, San Francisco, Ca 94102
 Ph: (415) 888-8580 Fx:(866) 260-5454
CORNER RECORD



LEGEND

- SUBJECT BOUNDARY LINES PER R1
- OTHER BOUNDARY LINES PER R1
- MONUMENT LINES PER R1
- EASEMENT LINES PER R1
- FOUND STANDARD WELL MONUMENT PER R1
- SET #4 REBAR & PLASTIC CAP LS 8080
- SET NAIL & TAG LS 8080 AS NOTED
- SUBDIVISION MAP: VOL 11, PAGE 61

