


CORNER RECORD

Document Number APN 200-231-02

City of MILL VALLEY

County of MARIN, California

Brief Legal Description LOT 2, 12 RM 77



CORNER TYPE

Government Corner  Control   
Meander  Property   
Rancho  Other   
Date of Survey 9-12-07

COORDINATES (Optional)

N. \_\_\_\_\_  
E. \_\_\_\_\_  
Zone \_\_\_\_\_ NAD27  NAD83   
NAD83 Epoch \_\_\_\_\_  
Elev. \_\_\_\_\_  
Vert. Datum: NGVD29  NAVD88   
Meas. Units: Metric  Imperial

Corner - Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:


FOUND STANDARD STREET WELL MONUMENT WITH BRASS PIN IN CONCRETE AS SHOWN ON  
12 RM 77 AND ON REVERSE.

A description of the physical condition of the monument as found and as set or reset: SET 3/4" IRON PIPES  
TAGGED PLS 5296 AND SET NAIL AND TAG PLS 5296 IN NW'LY BASE OF 20" PINE AS SHOWN  
ON REVERSE.

SURVEYOR'S STATEMENT

This Corner record was prepared by me or under my direction in conformance with  
the Land Surveyor's Act on SEPTEMBER 20, 2007

Signed [Signature] P.L.S. or R.C.E. No. PLS 5296



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received SEPTEMBER 1, 2011

and examined and filed SEPTEMBER 1, 2011

Signed COUNTY SURVEYOR P.L.S. or R.C.E. No. 7128

Title COUNTY SURVEYOR

County Surveyor's Comment \_\_\_\_\_



