


CORNER RECORD

Document number A.P.N. 005-122-06

City of SAN ANSELMO County of MARIN, California

Brief Legal Description BEING LOT 6, IN BLOCK 3, AS SHOWN UPON 5 R.M. 50,
MARIN COUNTY RECORDS



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey _____

COORDINATES

N. _____
E. _____
Zone _____ Datum _____
Elev. _____

Corner-- Left as found found and tagged Established Reestablished Rebuilt


Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
UTILIZED MONUMENTS AS SHOWN UPON RECORD OF SURVEY, 2007 O.S. 59, AS A
BASIS OF BEARINGS TO MONUMENT PROPERTY LINE POINTS OF SAID LOT 6 AS SHOWN
UPON ATTACHED DRAWING.

A description of the physical condition of the monument as found and as set or reset.
FOUND MONUMENTS PER 2007 O.S. 59.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on February 9 2009.

Signed [Signature] L.S. Number 7744



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received FEBRUARY 10, 2009 and examined
and filed MARCH 16, 2009.

Signed [Signature] Title COUNTY SURVEYOR

County Surveyor's Comment _____



SCALE: 1" = 20'

BLOCK 5
5 R.M. 64

Set Nail & Tag, PLS 7744
in Lower Fence Runner
0.61' from Corner

$R = 650.00' L = 60.19'$
 $D = 05^{\circ}18'21''$

GAZEBO

110.00' TOTAL

Set Hub & Tag, PLS 7744

LOT 6

2007 O.S. 59

Found Nail & Tag, PLS 7744
Top of Wood Fence
Per 2007 O.S. 59

MAP OF HAWTHORN HILLS
NO. 2

BLOCK 3
5 R.M. 50

32.00'
CONCRETE SWALE

Found 1/2" Rebar
& Cap, PLS 7744
Per 2007 O.S. 59

$R = 540.00' L = 50.00'$
 $D = 05^{\circ}18'19''$

RUTHERFORD AVENUE (40' R/W)

