


CORNER RECORD

Document Number APN 5-172-72

City of: San Anselmo
Brief Legal Description: Lot 87 & 88, Morningside Court
Map No. 2 (5 M 35)

County of Marin, California

Humann Company Job No.: 07128



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey: 9/07

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

- FOUND STANDARD MARIN COUNTY MONUMENT PER RECORD MAP
- FOUND 5/8" REBAR OR 3/4" IRON PIPE, AS NOTED
- SET 5/8" STEEL BAR W/ PLASTIC CAP, PLS 5452
- SET HUB AND TAG, PLS 5452


A description of the physical condition of the monument as found and as set or reset: _____

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the

Land Surveyor's Act on September 5, 2007

Signed Eric (Rick) A. Humann P.L.S. or R.C.E. No. 5452



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received OCTOBER 10, 2007

and examined and filed DECEMBER 10, 2007

Signed [Signature] P.L.S. or R.C.E. No. 7128

Title County Surveyor



County Surveyor's Comment _____

SEE REVERSE SIDE

