


CORNER RECORD

Document Number A.P.N. 005-191-30

City of SAN ANSELMO

County of MARIN, California

Brief Legal Description PTN. LOT 6, 3 R.M. 7B AS DESCR. IN D.R. 93-097094



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey 9-30-97

COORDINATES (Optional)

N. _____
E. _____
Zone _____ Datum _____
Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

= SEE OVER =

A description of the physical condition of the monument as found and as set or reset:

=SEE OVER=

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on DECEMBER 8 19 97.

Signed David Contreras L.S. or R.C.E. Number L.S. 5065



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received DECEMBER 15 19 97 and examined and filed DECEMBER 16 19 97.

Signed John M. Wooley Title DEPUTY



County Surveyor's Comment _____

A.P.N. 005-191-05

A.P.N. 005-191-06
N53°35'W
49.931'

3 R.M. 78
A.P.N. 005-191-07

A.P.N. 005-191-29

RE-SET 3/4" IRON PIPE, L.S. 5065
(DISPLACED DURING FENCE CONSTRUCTION)
S 39°08'09"W 155.450'

33.05.80

A.P.N. 005-191-30

N 58°35'E 191.80'

A.P.N. 005-191-23

REPLACED NAIL & TAG, L.S. 5065,
WITH 3/4" IRON PIPE, L.S. 5065

40'

17°36'E
61.932'
SAN ANSELMO AVENUE

MOND AVENUE

AVENUE

40'

