


# CORNER RECORD

Agency Index

Post CONST  
DRW# 19-151  
APN 005-204-37 ADJ

City of SAN ANSELMO County of MARIN, California  
Brief Legal Description STREET MONUMENT IN CAN PER CORNER RECORD (APN 005-204-37)



### CORNER TYPE

Government Corner  Control   
Meander  Property   
Rancho  Other   
Date of Survey 09/12/2019

### COORDINATES (Optional)

N. \_\_\_\_\_ E. \_\_\_\_\_  
Elevation \_\_\_\_\_  
Units Metric  U.S. Survey Foot   
Horizontal Datum \_\_\_\_\_  
Zone \_\_\_\_\_ Epoch Date \_\_\_\_\_  
Vertical Datum \_\_\_\_\_

Complies with Public Resources Code §§8801-8819  
 Complies with Public Resources Code §§8890-8902

PLS Act Ref.:  8765(d)  8771  8773  Other:

Corner/Monument:  Left as Found  Established  Rebuilt  Pre-Construction  
 Found and Tagged  Reestablished  Referenced  Post-Construction

Narrative of corner identified and monument as found, set, reset, replaced, or removed:

See sheet #2 for description(s):

USING FOUND MONUMENT REFERENCE POINTS PER CORNER RECORD (APN 005-204-37), INSTALLED A STANDARD STREET MONUMENT IN CAN, 3" DISK PUNCHED AND STAMPED (LS 7893), REPLACING ORIGINAL STREET MONUMENT. WORK WAS DONE AFTER THE COMPLETION OF THE SAN FRANCISCO BLVD PAVEMENT PROJECT (SEE PAGE 2 OF 2).

### Surveyor's Comment

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on NOVEMBER 4, 2019.

Signed [Signature] P.L.S. or R.C.E. No. LS 7893



### County Surveyor's Comment

This Corner Record was received DECEMBER 30, 2019 and examined and filed JAN. 30, 2020.

Signed [Signature] P.L.S. OR R.C.E. NO. 9292

Title DEPUTY C.S.



County Surveyor's Comment \_\_\_\_\_