


CORNER RECORD

Document Number 005-251-19
City of San Anselmo County of Marin, California

Brief Legal Description Lot 28 of 9 RM 39



CORNER TYPE

- Government Corner
- Meander
- Rancho
- Date of Survey _____
- Control
- Property
- Other

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
Found Standard street monuments per 9 RM 39

A description of the physical condition of the monument as found and as set or reset:
Set 1/2" rebars and plastic cap embossed LS 5290 (over)

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on 12/10/07

Signed David Harp L.S. or R.C.E. Number 5290




COUNTY SURVEYOR'S STATEMENT

This Corner Record was received DECEMBER 13, 2007 and examined and filed JANUARY 9, 2008

Signed _____ Title COUNTY SURVEYOR



County Surveyor's Comment _____



" SKETCH MAP "
(not to scale)

Found Monument

Indicates Set
1/2" bar & cap
LS 5290 (typ.)

OAK SPRINGS UNIT ONE

Sheet 27

28

27

Drainage & Utility Easement
N 81° 12' 32" E 116.12'

OAK SPRINGS
N 6° 18' W 257.00'

Found Monument

AVENUE

TIMOTHY

