


CORNER RECORD

Document Number 005-273-04

City of San Anselmo County of Marin, California

Brief Legal Description: Lot 61 of 10 RM 92



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey 03/17/08

COORDINATES (Optional)

N. _____
E. _____
Zone _____ Datum _____
Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Found original lot corners per 10 RM 92 & 11 RM 40

A description of the physical condition of the monument as found and as set or reset:

Found 1" Iron Pipes and tags RCE 9626 as indicated on attached sketch map. Set 1/2 rebar & cap LS 5290 line stake.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on 03/17/08

Signed David Harp L.S. or R.C.E. Number LS 5290




COUNTY SURVEYOR'S STATEMENT

This Corner Record was received MARCH 20, 2008 and examined

and filed APRIL 30, 2008

Signed _____ Title COUNTY SURVEYOR



County Surveyor's Comment _____

