


CORNER RECORD

Agency Index CR23-004
 Document Number APN 005-282-17

City of SAN ANSELMO County of MARIN, California
 Brief Legal Description LOT 57, 10 MAPS 90

CORNER TYPE

COORDINATES (Optional)



Government Corner Control N. _____ E. _____
 Meander Property Elevation _____
 Rancho Other Units Metric U.S. Survey Foot
 Date of Survey APRIL 10, 2022 Horizontal Datum _____
 Zone _____ Epoch Date _____
 Vertical Datum _____
 Complies with Public Resources Code §§8801-8819
 Complies with Public Resources Code §§88900-8902

PLS Act Ref.: **8765(d)** **8771** **8773** **Other:**
 Corner/Monument: Left as found Established Rebuilt Pre-Construction
 Found and tagged Reestablished Referenced Post-Construction

Narrative of corner identified and monument as found, set, reset, replaced, or removed:

See sheet #2 for description(s):

FOUND (1) IRON PIN SET IN CONCRETE IN MONUMENT WELL
 FOUND (2) 2.5" BRASS DISK SET IN CONCRETE IN MONUMENT WELL
 SET (4) 3/4" IRON PIPE WITH PLASTIC PLUG & TACK "LS 7735"

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
 the Professional Land Surveyor's Act on JANUARY 31, 2023
 Signed *Troy J. Erickson* P.L.S. or R.C.E. No. LS 7735



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received January 31, 2023
 and examined and filed February 01, 2023
 Signed *T.W. Park* P.L.S. ██████ No. 8176
 Title County Surveyor



County Surveyor's Comment:

