CORNER RECORD

Agency Index
Document Number

PRE-CONSTRUCTION

DPW # 18-077

APN 006-021-02 ADJ

COMMENTALCOND	Document Number ATN 006-021-02 AD
City of SAN ANSELMO	County of, California
Brief Legal Description FOUND PK NAIL IN ASPHALT P (2005 ROS 141), (2008 ROS 5	AVEMENT PER (32 ROS 45), (36 ROS 99),
CORNER TYPE Government Corner Control Meander Property Rancho Other Date of Survey 09/12/2018	COORDINATES (Optional) N E Elevation Units Metric [U.S. Survey Foot [] Horizontal Datum
	☐ Complies with Public Resources Code \$\$8801-8819 ☐ Complies with Public Resources Code \$\$8890-8902
PLS Act Ref.:	☐ 8773 ☐ Other:
Corner/	_
Narrative of corner identified and monument as fo See sheet #2 for description(s): FOUND PK NAIL (NO TAG OR WASHER) IN ASPHALT	PAVEMENT PER (32 ROS 45), (36 ROS 99),
(2005 ROS 141), (2008 ROS 58), (2014 ROS 97).	
(PAGE 2 OF 2); MONUMENT MAY BE DISTURBED DU CONSTRUCTION IS COMPLETED AND WILL BE RESET	IF FOUND DISTURBED. SEE NOTE ON (PAGE 2 OF 2).
Surveyor's Comment This Corner Record was prepared by me or under my directive the Land Surveyors' Act on	No. 7893 TV
County Surveyor's Comme	ent COLAND SURV
This Corner Record was received Declarated	/ 1000 1 1
Signed P.L.S. O	
County Surveyor's Comment	

