CORNER RECORD

Agency Index

~				
100	1	18-	NT	0
DPW	1	105	-01	0
- 1 0-			•	_

PRE-CONSTRUCTION

Document Number APN 006-031-17 ADT SAN ANSELMO County of MARIN ___ . California City of ___ Brief Legal Description FOUND RAILROAD SPIKE IN ASPHALT PAVEMENT PER (11 PM 75), (32 ROS 45), (36 ROS 99), (2005 ROS 141), (2014 ROS 97) COORDINATES (Optional) CORNER TYPE E. ____ Elevation Government Corner Control Metric □ U.S. Survey Foot □ Units Meander Property X Rancho Other Horizontal Datum Date of Survey 09/12/2018 Zone Epoch Date Vertical Datum __ Complies with Public Resources Code \$\$8801-8819 Complies with Public Resources Code \$\$8890-8902 Other: 8771 8773 X 8765(d) PLS Act Ref.: X Pre-Construction Left as Found Established Rebuilt Corner/ Monument: X Referenced ☐ Post-Construction ☐ Found and Tagged ☐ Reestablished Narrative of corner identified and monument as found, set, reset, replaced, or removed: X See sheet #2 for description(s): FOUND RAIL ROAD SPIKE (WITH CUT CROSS, NO TAG OR WASHER) IN ASPHALT PAVEMENT PER (11 PM 75), (32 ROS 45), (36 ROS 99), (2005 ROS 141), (2014 ROS 97). MONUMENT IS REFERENCED AS SHOWN ON (PAGE 2 OF 2); MONUMENT MAY BE DISTURBED DURING CONSTRUCTION; TO BE CHECKED AFTER CONSTRUCTION IS COMPLETED AND WILL BE RESET IF FOUND DISTURBED. SEE NOTE ON (PAGE 2 OF 2). Surveyor's Comment This Corner Record was prepared by me or under my direction in conformance with No. 7893 the Land Surveyors' Act on NOVEMBER 27, 20 18 P.L.S. or R.C.E. No. LS 7893 SUNSED LAND SURVEY County Surveyor's Comment This Corner Record was received DECEMBER 3, 2018 SEMERAD and examined and filed DEC. 20, 2018 P.L.S. OR R.C.E. NO. <u>9292</u> Signed_ County Surveyor's Comment_____

