


CORNER RECORD

Document Number A.P. # 6-114-02

City of SAN ANSELMO

County of MARIN, California

Brief Legal Description S.W. COR., LOT 2, BK 10, AMENDED MAP OF SEQUOIA PARK SECTION 2, 4 MAPS 21



CORNER TYPE

Government Corner ☐ Control ☐
Meander ☐ Property ☒
Rancho ☐ Other ☐
Date of Survey _____

COORDINATES (Optional)

N. _____
E. _____
Zone _____ Datum _____
Elev. _____

Corner — Left as found ☐ Found and tagged ☐ Established ☐ Reestablished ☐ Rebuilt ☒

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

FOUND 2" X 2" REDWOOD HUB IN DETERATING
CONDITION, L.S. 2771 TAG (SET IN 1970)
FROM ORIGINAL ANGLE POINT STAKE IN
LOT 2, BLOCK 10.

A description of the physical condition of the monument as found and as set or reset: RE SET
2" X 2" HUB WITH 3/4" METAL ROD WITH
2" ALUMINUM CAP STAMPED L.S. 2771
SEPT. 10, 1992

San Anselmo

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on OCT 15 1992.


Signed Paul B. Neese L.S. or R.C.E. Number 2771



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 10/20 1992 and examined and filed 10/21 1992.

Signed Robert Darrell Beaumont Title SE



County Surveyor's Comment _____

