


CORNER RECORD

Agency Index

DPW #19-134

Document Number

006-152-66

City of SAN ANSELMOCounty of MARIN, CaliforniaBrief Legal Description LOT 62 PER 6 RM 83**CORNER TYPE**

Government Corner ☐ Control
Meander ☐ Property
Rancho ☐ Other

COORDINATES (Optional)

N. _____ E. _____

☐ Elevation _____☒ Units Metric ☐ U.S. Survey Foot ☒☐ Horizontal Datum _____

Zone _____ Epoch Date _____

Vertical Datum _____

Date of Survey 10-24-19☐ Complies with Public Resources Code §§8801-8819☐ Complies with Public Resources Code §§8890-8902PLS Act Ref: ☒ 8765(d)☒ 8771☒ 8773☐ Other:Corner/Monument: ☐ Left as found☒ Established☐ Rebuilt☐ Pre-Construction☐ Found and tagged☐ Reestablished☐ Referenced☐ Post-Construction

Narrative of corner identified and monument as found, set, reset, replaced, or removed:

☒ See sheet #2 for description (s):**SEE SHEET 2****SURVEYOR'S STATEMENT**

This Corner Record was prepared by me or under my direction in conformance with

the Professional Land Surveyors' Act on November 13th, 2019RENEWED 12-30-2019.Signed _____ P.L.S. or R.C.E. No. 6649**COUNTY SURVEYOR'S STATEMENT**This Corner Record was received NOV. 13, 2019and examined and filed JAN. 30, 2020Signed [Signature] P.L.S. or R.C.E. No. 9292Title DEPUTY C.S.

County Surveyor's Comment _____

