CORN	ER REC	CORD	Agency Index	20-028
OOM		OND	Document Number	006-221-31
City of SA	N ANSELMO	County of	MARIN	, California
Brief Legal Description PARCEL 2, 18 PM 11				
	CORN	ER TYPE		ATES (Optional)
board board board	Government Corner		N.	
		Control	Elevation	
	Meander	X Property		U.S. Survey Foot X
Brangered Brangered	Rancho	Other	Horizontal Datum	
	Data of Comme	14 00 0040	ZoneEpoch	
	Date of Survey	May 20, 2019	_Vertical Datum	
			Complies with Public Resources Code §§8801-8819 Complies with Public Resources Code §§8890-8902	
			Compiles with Public Re	esources Code 998890-8902
PLS Act Ref.:	8765(d)	8771	8773	Other:
Corner/	Left as found	Established	Rebuilt	Pre-Construction
Monument:	Found and tagged	Reestablished	Referenced	Post-Construction
Narrative of corner identified and monument as found, set, reset, replaced, or removed: See sheet #2 for description(s):				
We found the survey monuments at the northeasterly and southeasterly corners of Parcel 2, 18 PM				
11, both were 3/4" iron pipes and caps LS 3775(see plat). It is assumed that the 2x3" stake point was replaced with a pipe by J. Grippi but no record exists. Line Stakes set (see plat)				
replaced with a pipe by J. Grippi but no record exists. Zine States act (See plant)				
				SED LAND SURV
SURVEYOR'S STATEMENT				
12/9, w/s/				
This Corner Record was prepared by me or under my direction in conformance with				
the Professional Land Surveyors' Act on May 18, 2020				
Signed Sand?	1	DI 0 - D0 F N	DI C ESOO	10, 5290 NA
Signed X Juliu / /	, sh	P.L.S. or R.C.E. No.	PLS 5290	E OF CALIFORN
	1			
COUNTY SURVEYOR'S STATEMENT				
	JOON! I CONVETON	JOIAILMILMI		
This Corner Record was received JUNE 08, 2020				
S. CHA S. W. S. C.				
and examined and filed Aug. 11, 2020				
Signed (L	2	P.L.S. or R.C.E. No.	9292	a 27/11/0

ADEI SC-2018

Title

DEPUTY C.S.

County Surveyor's Comment

