


# CORNER RECORD

Document Number A.P. # 6-254-35  
 City of San Anselmo County of Marin, California  
 Brief Legal Description PM 12-67



## CORNER TYPE

Government Corner ☐ Control ☐  
 Meander ☐ Property ☒  
 Rancho ☐ Other ☐  
 Date of Survey \_\_\_\_\_

## COORDINATES (Optional)

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone \_\_\_\_\_ Datum \_\_\_\_\_  
 Elev. \_\_\_\_\_

Corner — Left as found ☐ Found and tagged ☐ Established ☐ Reestablished ☒ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

FOUND EXISTING CORNERS PER PM 12-67  
SEE MAP ON REVERSE SDE

A description of the physical condition of the monument as found and as set or reset:

Set 5/8" Rebar  
\$ CAP RCE 18200

## SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on 4-17 1997.


Signed Douglas J. Matteson L.S. or R.C.E. Number 18200



## COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JUNE 16 1997 and examined and filed JUNE 18 1997.

Signed John M. Woolley Title Deputy



County Surveyor's Comment \_\_\_\_\_

DOUGLAS J. MATTESON  
 CIVIL ENGINEER & LAND  
 SURVEYOR  
 200 GATE 5 RD. #208  
 SAUSALITO CA. 94965  
 332 7614

1" = 20'

