


CORNER RECORD

Document Number I.N. 2005-0049316

City of SAN ANSELMO County of MARIN, California
Brief Legal Description LOT 1, OF PARCEL MAP RECORDED IN BOOK 21 OF PARCEL MAPS, AT PAGE 99, MARIN COUNTY RECORDS



CORNER TYPE
Government Corner [] Control []
Meander [] Property []
Rancho [] Other []
Date of Survey 23 DECEMBER 2014

COORDINATES (Optional)
N.
E.
Zone NAD27 [] NAD83 []
NAD83 Epoch
Elev.
Vert. Datum: NGVD29 [] NAVD88 []
Meas. Units: Metric [] Imperial []

Corner - Left as found [] Found & tagged [] Established [] Reestablished [] Rebuilt []


Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish corner:
FOUND 3/4" IRON PIPES WITH NAIL & TAG "LS 2738" PER BOOK 19 OF PARCEL MAPS, AT PAGE 98, MARIN COUNTY RECORDS, AS SHOWN UPON REVERSE SIDE.

A description of the physical condition of the monument as found and as set or reset: AS SHOW UPON REVERSE SIDE.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on 23 DECEMBER 2014.

Signed P.L.S. No. 4794



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received January 15, 2015 and examined and filed March 16, 2015

Signed P.L.S. or R.C.E. No. 7821

Title Deputy



County Surveyor's Comment



PREPARED BY
PHILLIP A. DANSKIN & ASSOCIATES

LAND SURVEYOR
SONOMA, CALIFORNIA
PHONE : (707) 938-2520

SURVEY No. 1022

FOR : Robert & Sylvie Reynolds
80 Summit Road
San Anselmo, California

○ Set 3/4" I.D. galvanized iron pipe with plastic plug
"DANSKIN PLS 4794" with tee iron guard, unless
noted otherwise

● Found 3/4" I.D. iron pipe with nail & tag "LS 2738"
per 19-PM-98, unless noted otherwise

