
CORNER RECORD	Document N	lumber <u> <i>AP</i></u>	<u>N 009-07</u>	70,080
City of San Rafael	County of _	Marin		, California
Brief Legal Description <u>Perpetuate & Re-Establish intersection of Catalina & </u>	the Street Mo Canal per 12 R	nument R.M. 55;	<u>93' South</u> Marin Cou	west of the inty Records
Meander □	Control	N, E, Zone_, NAD83Epoch _. Elev,		□ NAD83 □
Corner - Left as found ☐ Found and tagged ☐	l Established □	Reestab	lished ⊠	Rebuilt 🗆
Identification and type of corner found: Evidence used to identifulation and type of corner found: Evidence used to identifulation and to construction and to redetermine the validity of the monument or lines in the area.	93 feet Southw Canal St.) was l establish its po	vest of t ocated t sition No	he interse o perpetu o attempt	ction of ate its position was made to
A description and the physical condition of the monument as for				73444
The existing brass disk in a Standard City S				
location was found in good condition prior to				
re—established and rebuilt with a 3" Alumin "Replaced by Corner Record"	um visk punche	ea & Sta	mpea PL	3 8118
Replaced by Corner Record			***************************************	
This Corner Record was prepared by me or under my direction the Land Surveyor's Act on May 28, 2009 Signed P.L.S. or R.C.E. No.) —	//8	RANDALL T. WILLIS PLS 8118 Exp. 12/31/10
COUNTY SURVEYOR'S STATEME	NT		\mathred in the second	OF CALIFO
This Corner Record was received June 12, 2000	7		f !	A DATE OF THE PROPERTY OF THE
and examined and filed July 16, 2009		······	· .	TACA PL
Signed P.L.S. or R.C.E. N	o. <u>7128</u>		/ \$	B WO
Title COUNTY SURVEYOR			1	Exp. 12-31-10 *
County Surveyor's Comment			e de la companya de l	No. (128
		· · · · · · · · · · · · · · · · · · ·		The Action of the Control of the Con
			ina.	



Page 2 of 2