CORNER RECORD	Document Number	r I.N. 95-42508
City of San Rafael	County ofMART	N , Californ
Brief Legal Description I.N 95-42508		
CORNER 1	「YPE Control □ Property XX	COORDINATES (Optional) N E
Rancho Date of Survey	Other	Zone Datum Elev
Corner — Left as found (A) Found and tagged	Established [Reestablished Rebuilt R
Identification and type of corner found: Evidence used to A Found 1/2" square-head bolt, 16	o identify or procedure used eft as found	to establish or reestablish the comer:
B Found old hub with 2 galvanized	d nails	
A description of the physical condition of the monumen	t as found and as set or re	set*
B) Replaced hub with 3/4" I.D. gal	lvanized iron pipe	with plastic plug "PLS 4794"
		GED LAND SUM
SURVEYOR'S STATEMEN	Т	
This Corner Record was prepared by me or under my the Land Surveyors' Act on December 4,	direction in conformance $\frac{98}{}$.	with A Phillip A. Danskin No. 4794 Expiresses 80-
1 M / X I	. Number <u>LS 4794</u>	TE OF CALLED
COUNTY SURVEYOR'S STATE	MENT	PROFESSIONA
This Corner Record was received <u>December</u> &	2 19 <u>98</u> and exam	ined Sign Wi. WOO
and filed Deckmber 9, 1998.		No. 26450 Exp. 3-31.60
Signed foun M. Moday	Title <u>DEPUTY</u>	— CIVIL OF PAHE
County Surveyor's Comment		VIL
		. Ju.

