CORNER RECORD	Document Number _	AP No. 010-154-047
City of San Rafael	County of Marin	, Californ
Brief Legal Description Lot 4, 25 PM 36, Being a Resu		of Laurel Properties
CORNER TYPE		COORDINATES (Optional)
Meander 🗌	Control Property Other	N E Datum Zone Datum
Corner — Left as Found Found and tagged	Established 🗌 R	Reestablished M Rebuilt 🗌
Identification and type of corner found: Evidence used to ident		
Set and found monument at record bearings and d Parcel Map, filed in Book 25 of Parcel Maps, page	7	nd monumentation as shown
See diagram on reverse side of this form (page 2		
See diagram on reverse side of this form (page 2	01 2).	
		Set 1/2" Iron Dines
A description of the physical condition of the monument as f	found and as set or res	et: Set 1/2 Holl Pipes,
Tagged LS 5092, and found 1/2" Rebars with yell		8 6 135.
See diagram on reverse side of this form (page 2	2 OT 2).	
	· .	
<u> </u>		
GUDVEYODIS STATEMENT		LAND SU
SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direct the Land Surveyors' Act on July 17	ction in conformance	WITE BUTI OR
the Land Suprevers' Act on July 17	2000	\(\frac{1}{\pi}\) \(\frac{1}{\
the Land Surveyors Act on	, 2000.	Exp. 6-30-2003
Signed LS 5092		FOF CALIFOR
COUNTY SURVEYOR'S STATEMEN	NT .	PROFESSIONAL NAME OF THE PROPERTY OF THE PROPE
This Corner Record was received July 28	2000 and exam	nined Strong M. Wood
and filed July 31 7000.	0 = -	No. 26450 Exp. 03-31-04
Signed Aus Wir Works Tit	tle DEPUTY	OF CALIFORNIA
County Surveyor's Comment		
County Cartegor & Commont		

