



JERRICO ASSOCIATES

SUITE 27
77 MARK DRIVE
SAN RAFAEL, CA 94903

7527


see 7044

CORNER RECORD

Document Number 11-033-09 Repeat

City of San Raphael County of Marin, California

Brief Legal Description Lot 20, Map of Chula Vista Terrace 4 RM 27



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey Sept. 28, 2004

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
Based on found points along back line of Lots

19 & 20 as re-set as in 15 O.S. 18

- (A) Re-find pipe & LS 2897 (disturbed).
- (B) Re-find hub & nail in depression. Set tag LS 3887.
- (C) Re-find open pipe (not on rear line).

A description of the physical condition of the monument as found and as set or reset: _____

- (D) (E) Set rebar and cap LS 3887.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on Sept. 28, 2004

Signed [Signature] P.L.S or R.C.E. No. LS 3887

COUNTY SURVEYOR'S STATEMENT


This Corner Record was received OCTOBER 29, 2004


and examined and filed NOVEMBER 17, 2004

Signed [Signature] P.L.S or R.C.E. No. 7128

Title COUNTY SURVEYOR

County Surveyor's Comment _____





S-7527